# Weathertzation Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/50005DE0063/1
Work Order Type: Weatherization
Audit Name: Audit DE0063

#### **CLIENT INFORMATION**

Client Name: Address:

Client ID: 50005DE0063 , TN

Alt. Client ID:

#### **AGENCY INFORMATION**

**Agency:** 50005DE **Agency Phone:** (901) 476-5226

**Address:** P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

**Email Address:** 

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

Measure 1

Infiltration Redctn

#### Comment Baseline .7 - Rainy - 75 Degrees - Test done at front door AIR INFILTRATION MEASURES: 1. Patch hole Master bedroom wall - near vanity 2. Block around two exhaust fans 3. Repair attic stairs 4. Air Seal Lighting junction boxes 10 5. Air Seal around cielings 6. air Seal Plumbing Penetrations - Kitchen - Bathroom - vanity & laundry 7. Weatherstrip attic door after repair 8. Wrap 11 boots and seal with Mastic sealer and tape 9. Caulk all windows on the inside of house and outside 10. Air seal around baseboards. 11. Patch Ceiling above gas water heater **Estimated** Actual # Material / Labor Total **Unit Cost Description / Comment Units Unit Cost Total** Qty Qty 10 Miscellaneous Infiltration Reduction Each 1 Supplies Other Detail Sub Total: Measure Sub Total: Field Notes:

**Components** 

Report Run On: 5/27/2010

Inspected

Measure 2 DW	/H Pipe Insulation	Components				Inspected		
<b>Comment</b> water h	neater located in unheated gs	l utlity rooi	m - nee	ed to replace	e - high C	0		
			Estimated					
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						1		
			Measur	e Sub Total:		,	Sub Total:	
Measure 3 Att Comment 400 Sc	ic Ins. R-38 I.ft has cathedral cielings			Componen Estimated		F	Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	 Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	900		rotur	Qty		rotar
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 5/27/2010

Measure 4 Stor	Measure 4 Storm Windows Components			ts Front			Inspected	
Comment ALL WIN	NDOWS ARE DOUBLE	PANES						
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	SqFt	48					
2 Labor	Storm Window	SqFt	48					
3 Other	Storm Window	Each Window	3					
Other Detail								
		ı	Measur	e Sub Total:			Sub Total:	
Measure 5 A/C	Tuneup			Componen  Estimated		al	Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	T- (-1
1 Cooling Equipment	: A/C Tuneup	Each	1					Total
2 Labor								Iotal
	A/C Tuneup	Each	1					Iotal
Other Detail	A/C Tuneup	Each	1					Total
Other Detail	A/C Tuneup	Each	1					Total
Other Detail	A/C Tuneup	Each	1					Total
Other Detail	A/C Tuneup			e Sub Total:			Sub Total:	Iotal

Measure 6 CO	Monitor is Needed			Componen	ts		-	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
<ol> <li>Health and Safety Items</li> </ol>	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:		]	Sub Total:	
(Wat	Any Other Venting Relater Heat) eater located in unheated			Componen		0	ı	Inspected
readings	3			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety     Items	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 5/27/2010